PAGE: 1 PRINT DATE: 11/16/01

#### FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL HARDWARE

NUMBER: 03-1-0216 -X

SUBSYSTEM NAME: MAIN PROPULSION

**REVISION:** 2 08/08/00

PART DATA

PART NAME PART NUMBER
VENDOR NAME VENDOR NUMBER

LRU :LH2 4" DISCONNECT CLOSING SOLENOID

VALVE, TYPE 2

MC284-0404-0032, -0042

UNITED SPACE ALLIANCE - NSLD 13111-5, -6

#### **EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

VALVE, SOLENOID, NORMALLY CLOSED 3-WAY, 1/4 INCH. LH2 RECIRCULATION DISCONNECT CONTROL. CLOSING.

VALVE WAS ORIGINALLY DESIGNED AND MANUFACTURED BY WRIGHT COMPONENTS (NOW PERKIN ELMER) BUT IS NOW MANUFACTURED BY UNITED SPACE ALLIANCE-NSLD AS AN ALTERNATE PRODUCTION AGENCY.

**REFERENCE DESIGNATORS**: LV51

**QUANTITY OF LIKE ITEMS:** 1

## **FUNCTION:**

CONTROLS PNEUMATIC PRESSURE TO CLOSE THE 4" LH2 RECIRCULATION DISCONNECT VALVE (PD3). THE OPEN SOLENOID (LV50) MUST DEACTUATE TO ALLOW THE DISCONNECT ACTUATOR TO VENT SO THE DISCONNECT CAN BE CLOSED. CLOSING SOLENOID (LV51) (REFERENCE FMEA/CIL 03-1-0215) IS NORMALLY DEACTUATED TO ALLOW VALVE TO OPEN, BUT THE DISCONNECT ACTUATOR IS BIASED OPEN (WITH PRESSURE APPLIED, THE OPEN SIDE WILL WIN FORCE FIGHT). THE DISCONNECT IS COMMANDED OPEN PRIOR TO ENGINE CONDITIONING AND COMMANDED CLOSED UPON ENGINE SHUTDOWN.

PAGE 2 PRINT DATE: 11/27/01

### FAILURE MODES EFFECTS ANALYSIS FMEA -- CIL FAILURE MODE

NUMBER: 03-1-0216-04

**REVISION#**: 2 08/09/00

SUBSYSTEM NAME: MAIN PROPULSION

LRU: LH2 4" DISC CLOSE SOLENOID VALVE (LV51)

ITEM NAME: LH2 4" DISC CLOSE SOLENOID VALVE (LV51)

FAILURE MODE: 1R3

## **FAILURE MODE:**

PREMATURE ACTUATION (RECIRC DISCONNECT FAILS TO REMAIN OPEN, REFERENCE FMEA/CIL 03-1-0405-02) CAUSING ACTUATOR CLOSING SIDE TO PRESSURIZE. PRIOR TO ORBITER/ET UMBILICAL SEPARATION.

MISSION PHASE: PL PRE-LAUNCH

LO LIFT-OFF

**VEHICLE/PAYLOAD/KIT EFFECTIVITY:** 102 COLUMBIA

103 DISCOVERY104 ATLANTIS105 ENDEAVOUR

#### CAUSE:

PIECE PART STRUCTURAL FAILURE, SEAL/SEAT DAMAGE

**CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO** 

**REDUNDANCY SCREEN** A) PASS

B) FAIL C) PASS

### **PASS/FAIL RATIONALE:**

A)

B)

FAILS B SCREEN BECAUSE SOLENOID VALVES DO NOT HAVE POSITION INDICATORS.

C)

### - FAILURE EFFECTS -

## (A) SUBSYSTEM:

LOSS OF REDUNDANCY ONLY. FAILURE RESULTS IN APPLICATION OF ACTUATOR CLOSING PRESSURE. THE DISCONNECT VALVE IS BISTABLE WITH NEITHER SOLENOID PRESSURE APPLIED AND WILL REMAIN IN ITS LAST COMMANDED POSITION DUE TO ORBITER LATCH

PAGE: 3 PRINT DATE: 11/27/01

## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0216-04

AND ET LEVER CONTACT. OPENING PRESSURE IS NOMINALLY APPLIED FOR LOADING, DETANKING, AND ENGINE OPERATION.

#### (B) INTERFACING SUBSYSTEM(S):

SAME AS A.

### (C) MISSION:

NO EFFECT. VALVE WILL REMAIN OPEN.

### (D) CREW, VEHICLE, AND ELEMENT(S):

SAME AS C.

#### (E) FUNCTIONAL CRITICALITY EFFECTS:

1R/3 3 SUCCESS PATHS. TIME FRAME - ASCENT

- 1) PREMATURE ACTUATION OF DISCONNECT CLOSING SOLENOID (LV51).
- 2) PREMATURE DEACTUATION OF DISCONNECT OPENING SOLENOID (LV50).
- 3) RECIRCULATION MANIFOLD RELIEF VALVE (RV7) FAILS TO RELIEVE.

RESULTS IN RUPTURE OF THE RECIRCULATION SYSTEM. LOSS OF CRITICAL FUNCTIONS DUE TO ADJACENT COMPONENT EXPOSURE TO CRYOGENICS. POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND FIRE/EXPLOSION HAZARD.

ALSO RESULTS IN LOSS OF HELIUM SUPPLY DURING MANIFOLD REPRESSURIZATION CAUSING LOSS OF AFT COMPARTMENT PURGE. POSSIBLE LOSS OF CREW/VEHICLE.

### -DISPOSITION RATIONALE-

### (A) DESIGN:

VALVE IS DESIGNED FOR A PRESSURE FACTOR OF SAFETY OF 2.0 PROOF, 4.0 BURST. THE CLOSURE DEVICE IS A 430 CRES BALL ACTING UPON EITHER OF TWO VESPEL SEATS. THE VALVE FEATURES A BALANCED LOAD ON THE BALL BY APPLYING INLET PRESSURE (750 PSIG NOMINAL) DIRECTLY TO THE BALL AT THE INLET SEAT AND INDIRECTLY (VIA A BELLOWS) THROUGH THE VENT SEAT. THE BELLOWS IS ASSISTED BY A SPRING, THE FORCE OF WHICH INSURES THE BALL IS HELD SECURELY AGAINST THE INLET SEAT WHEN THE SOLENOID IS DEENERGIZED. UPON BEING ENERGIZED THE SOLENOID DEVELOPS THE FORCE TO OVERCOME THE SPRING LOAD AND SEATS THE BALL ONTO THE VENT SEAT TO ALLOW HELIUM FLOW. TOTAL POPPET MOVEMENT (STROKE) IS LESS THAN 0.040 INCH.

PREMATURE ACTUATION, FROM THE MECHANICAL VIEW, MEANS APPLICATION OF A DIFFERENTIAL FORCE TO THE VALVE BALL TO CAUSE IT TO MOVE FROM THE INLET SEAT TO THE VENT SEAT. ON THE SOLENOID SIDE OF THE BALL, NO MECHANICAL FAILURES WOULD CAUSE PREMATURE ACTUATION. ON THE OTHER HAND, IF THE CLOSING FORCE OF

PAGE: 4 PRINT DATE: 11/27/01

## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0216-04

THE BELLOWS/SPRING WERE REMOVED, INLET PRESSURE AND FLOW ACTING ON THE BALL WOULD DRIVE IT TO THE VENT SEAT, CAUSING PREMATURE ACTUATION.

THE FORCE TO HOLD THE BALL TO THE INLET SEAT, WHEN THE SOLENOID IS DEENERGIZED, IS PROVIDED BY THE BELLOWS ASSEMBLY AND SPRING THROUGH THE VALVE POPPET. IF THE BELLOWS FAILS, OR LEAKS TO THE POINT OF REDUCING THE BELLOWS INTERNAL PRESSURE TO LESS THAN THE VALVE INLET PRESSURE, THE LOAD BALANCING FEATURE IS ELIMINATED AND THE BALL WOULD MOVE TO THE VENT SEAT. THE BELLOWS IS MADE OF NICKEL-COBALT-COPPER AND IS PROOF PRESSURE TESTED AT 1550 PSIG PRIOR TO ASSEMBLY INTO THE VALVE.

IF THE SPRING BREAKS, THE PRESSURIZED BELLOWS WOULD EXERT SUFFICIENT FORCE TO RETURN THE BALL TO THE INLET SEAT; HOWEVER, SEAT LEAKAGE MAY RESULT. THE SPRING IS MADE FROM 17-7PH CRES (ELGILOY) WIRE AND IS HEAT TREATED FOLLOWING FORMING. IT HAS A SPRING RATE OF 13.5 POUNDS/INCH AND EXERTS A FORCE OF 7.54 POUNDS IN ITS INSTALLED CONDITION.

PREMATURE ACTUATION DUE TO SEAT/SEAL DAMAGE IS VERY UNLIKELY. THIS PRESUMES FLOW PAST THE SEATED BALL AT A RATE SUFFICIENT TO PRESSURIZE THE ACTUATION PORT TO A PRESSURE OF 400 PSIA MINIMUM, WHILE THE VENT PORT IS OPEN. THE BALL IS OF 430 CRES AND THE SEAT IS OF VESPEL.

THE -0032, -0042 CONFIGURATION SOLENOID VALVES ARE IDENTICAL TO THE -0012 CONFIGURATION WITH THE EXCEPTION OF ADDING THE FILTER (10 MICRON NOMINAL, 25 MICRON ABSOLUTE) IN THE VENT PORT OF THE SOLENOID VALVE AND REDESIGN OF THE VENT PORT CHECK VALVE. THIS FILTER WAS ADDED TO PREVENT CONTAMINATION AND METALLIC PARTICLES GENERATED DURING THE REMOVAL OF THE VENT PORT CHECK VALVE DURING OMRSD LEAKAGE MEASUREMENTS FROM ENTERING THE SOLENOID VALVE.

THE VENT PORT CHECK VALVE WAS REDESIGNED TO PREVENT THE POPPET FROM BEING EJECTED DUE TO SHEARING OF THE RETAINING NUT THREAD. A PIN WAS ADDED TO THE CHECK VALVE HOUSING, WHICH RETAINS THE POPPET WITHIN THE CHECK VALVE HOUSING. A NEW ALUMINUM NUT, WHICH PROVIDE A MINIMUM ENGAGEMENT OF THREE THREADS, WAS UTILIZED TO INCREASE RELIABILITY.

### (B) TEST:

ATP

AMBIENT TEMPERATURE TESTS

PROOF PRESSURE (1560 PSIG); EXTERNAL LEAKAGE (850 PSIG); ELECTRICAL CHARACTERISTICS AND RESPONSE; INTERNAL LEAKAGE (740 PSIG, ENERGIZED AND DEENERGIZED)

REDUCED TEMPERATURE TESTS (-160 DEG F)
ELECTRICAL CHARACTERISTICS AND RESPONSE; INTERNAL LEAKAGE

**ELECTRICAL BONDING TESTS** 

SOLENOID SUBASSEMBLY TESTS

PAGE: 5 PRINT DATE: 11/27/01

## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0216-04

ELECTRICAL CHARACTERISTICS; ENCLOSURE LEAKAGE (ONE ATMOSPHERE)

**CERTIFICATION** 

TWO UNITS -

PORT AND FITTING TORQUE

SALT FOG EXPOSURE FOLLOWED BY ELECTRICAL AND LEAKAGE CHECKS

#### AMBIENT VIBRATION TESTS:

TOTAL 13.1 HOURS BOTH AXES FOR TWO VIBRATION LEVELS PLUS TRANSIENT VIBRATION SWEEP - RUN WITH ONE SPECIMEN ENERGIZED AND ONE DEENERGIZED - FOLLOWED BY ELECTRICAL CHARACTERISTICS AND LEAKAGE CHECKS

HANDLING SHOCK TEST

**ENERGIZED AND DEENERGIZED FLOW TESTS** 

FIFTY HOUR CONTINUOUS CURRENT TEST AT 130 DEG F

AMBIENT TEMPERATURE ENDURANCE (4500 CYCLES FOLLOWED BY ELECTRICAL AND LEAKAGE CHECKS); 130 DEG F ENDURANCE (500 CYCLES FOLLOWED BY ELECTRICAL AND LEAKAGE CHECKS); OPERATION CYCLES (REPEATED 20 TIMES); REPEAT OF AMBIENT TEMPERATURE ENDURANCE; -160 DEG F ENDURANCE (500 CYCLES FOLLOWED BY ELECTRICAL AND LEAKAGE CHECKS).

DISASSEMBLY AND INSPECTION

BURST PRESSURE (3400 PSIG)

#### **GROUND TURNAROUND TEST**

ANY TURNAROUND CHECKOUT IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

# (C) INSPECTION:

RECEIVING INSPECTION

RAW MATERIALS ARE VERIFIED BY INSPECTION FOR MATERIAL AND PROCESSES CERTIFICATION. BODY HOUSING BAR STOCK IS ULTRASONICALLY INSPECTED.

#### **CONTAMINATION CONTROL**

CLEANLINESS LEVEL VERIFIED TO 100A. CORROSION PROTECTION IS VERIFIED BY INSPECTION.

### ASSEMBLY/INSTALLATION

10X MAGNIFICATION EXAMINATION OF ALL DETAIL PARTS FOR BURRS, DAMAGE AND CORROSION IS MADE PRIOR TO ASSEMBLY. ALL DETAIL PARTS ARE INSPECTED FOR DIMENSIONS. CRITICAL SURFACE FINISHES ARE INSPECTED USING A COMPARATOR AT 10X MAGNIFICATION. OTHER SURFACE FINISHES ARE INSPECTED AND VERIFIED WITH A PROFILOMETER. TORQUES ARE VERIFIED TO BE IN ACCORDANCE WITH DRAWING

PAGE: 6 PRINT DATE: 11/27/01

## FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0216-04

REQUIREMENTS. MANDATORY INSPECTION POINTS ARE INCLUDED IN THE ASSEMBLY PROCEDURE.

#### CRITICAL PROCESS

WELDING, HEAT TREATMENT AND PARTS PASSIVATION VERIFIED BY INSPECTION. POTTING OF SOLDER CUPS, ELECTRICAL WIRE STRIPPING, AND SOLDERING OF CONNECTORS ARE VERIFIED BY INSPECTION. CHROME PLATING AND DRY FILM LUBRICATION ARE VERIFIED BY INSPECTION.

#### NONDESTRUCTIVE EVALUATION

WELDS VISUALLY EXAMINED & VERIFIED BY X-RAY AND DYE PENETRANT INSPECTIONS. THE SOLENOID ASSEMBLY IS SUBJECTED TO LEAKAGE VERIFICATION USING RADIOACTIVE TRACER TECHNIQUES. SOME VALVE BODIES WERE SUBJECTED TO 10X MAGNIFICATION INSPECTION ONLY. OTHER VALVE BODIES WERE SUBJECTED TO EDDY CURRENT INSPECTION, IN ADDITION TO 10X MAGNIFICATION. THE REMAINING VALVE BODIES WERE SUBJECTED TO 10X MAGNIFICATION, ETCH AND DYE PENETRANT INSPECTIONS. REFURBISHED VALVE BODIES WERE SUBJECTED TO 40X MAGNIFICATION INSPECTION. BELLOWS ASSEMBLY IS PROOF PRESSURE TESTED AND LEAK CHECKED.

### **TESTING**

ATP VERIFIED BY INSPECTION.

#### HANDLING/PACKAGING

HANDLING, PACKAGING, STORAGE AND SHIPPING REQUIREMENTS ARE VERIFIED BY INSPECTION.

## (D) FAILURE HISTORY:

LEAKAGE RESULTING FROM SEAL/SEAT DAMAGE (OR CONTAMINATION) HAS OCCURRED BUT HAS NOT BEEN OF SUFFICIENT MAGNITUDE TO CAUSE PREMATURE ACTUATION (REFERENCE FMEA/CIL 0291-1, SOLENOID EXTERNAL LEAKAGE THROUGH VENT PORT).

CURRENT DATA ON TEST FAILURE, FLIGHT FAILURE, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

## (E) OPERATIONAL USE:

NO CREW ACTION CAN BE TAKEN.

PAGE: 7 PRINT DATE: 11/27/01

# FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE NUMBER: 03-1-0216-04

# - APPROVALS -

: W.P. MUSTY :/S/ W. P. MUSTY

S&R ENGINEERING ITM : P. A. STENGER-NGUYEN :/S/ P. A. STENGER-NGUYEN

DESIGN ENGINEERING : DAVE NEARY :/6/ PAVE NEARY DESIGN ENGINEERING : DAVE NEARY :/S/ DAVE NEARY
MPS SUBSYSTEM MGR. : TIM REITH :/S/ TIM REITH
MOD : BILL LANE :/S/ BILL LANE
USA SAM : MIKE SNYDER :/S/ MIKE SNYDER
USA ORBITER ELEMENT : SUZANNE LITTLE
NASA SR&QA : ERICH BASS :/S/ ERICH BASS